



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Arrowhead 9

API: 05-103-05301

Inspection: 700405198



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Arrowhead 9

API: 05-103-05301

Inspection: 700405198



40.06871, -108.79404, 5362.4ft, 135°
01/28/2021 10:08:00 AM



40.0687, -108.79402, 5347.3ft, 5°
12/28/2020 03:26:37 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Larkin nut on 12-28-2020.

Arrowhead 9

API: 05-103-05301

Inspection: 700405198





40.06872, -108.79402, 5361.1ft, 204°
01/28/2021 10:10:13 AM



40.06872, -108.79405, 5361.2ft, 6°
01/28/2021 02:28:12 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. Larkin nut on 1-28-2021 @ 14:28.

Arrowhead 9

API: 05-103-05301

Inspection: 700405198



40.06911, -108.79438, 5374.9ft, 356°
01/28/2021 10:14:45 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 8. Tank hatch.

Arrowhead 9

API: 05-103-05301

Inspection: 700405198



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 9. Tank.

Arrowhead 9

API: 05-103-05301

Inspection: 700405198



Photo 10

40.06914, -108.79434, 5355.2ft, 205°
01/28/2021 10:17:33 AM



40.06914, -108.79437, 5356.2ft, 182°

01/28/2021 10:17:09 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 11. View looking into bottom tank pipe.

Arrowhead 9

API: 05-103-05301

Inspection: 700405198