

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Fabricated fencing		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Fabricated fencing around gas meter run and separator		
Corrective Action:			Date:

Equipment:

Type	#		corrective date
Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Ancillary equipment	# 1		
Comment:			
Corrective Action:			Date:
Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

PRODUCED WATER	1	<50 BBLs	BV CONCRETE		
Comment: 50 BBL					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: May need to be addressed soon.				Date:
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		Date:
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 202126 Type: WELL API Number: 001-07531 Status: SI Insp. Status: SI

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____
 End Surf Csg Pressure: _____

Comment: Annual bradenhead test is not current. Contact COGCC engineering.

01/21/2021

Corrective Action: Comply with 341 c

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 1/1/21 at approximately 1255 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Horth R 2 Company Name- KPK API- 05-001-07531 In Adams County Colorado. While there, I observed Well Type During this inspection the following possible compliance issues were observed: Annual bradenhead test is not current. Contact COGCC engineering Comply with 341 c. 1/21/21 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. At time of inspection weather conditions were cold, sunny, recent snow. This is a summary of inspection report.</p>	medinaj	01/11/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402572376	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5327561
699502114	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5327552