

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/21/2021

Submitted Date:

01/21/2021

Document Number:

700702196

FIELD INSPECTION FORM

Loc ID 335118	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10531 Name of Operator: GRIZZLY OPERATING LLC Address: 5847 SAN FELIPE #3000 City: HOUSTON State: TX Zip: 77057				Findings: 16 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S
, Grizzly		aaxelson@grizzlyenergyllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260917	WELL	PR	03/01/2011	GW	045-07921	PORTER FEDERAL 16-29	PR
260919	WELL	PR	12/10/2008	GW	045-07923	PORTER FEDERAL 9-29	PR
285049	WELL	PR	11/06/2007	GW	045-12359	SHIDELER FEDERAL 44B-29-692	PR
285050	WELL	PR	11/03/2007	GW	045-12360	SHIDELER FEDERAL 43D-29-692	PR
285051	WELL	PR	11/04/2007	GW	045-12361	SHIDELER FEDERAL 43A-29-692	PR
291190	WELL	PR	12/09/2014	GW	045-14317	SHIDELER FEDERAL 44A-29-692	PR

General Comment:**COGCC Inspection Report Summary**

On Thursday 1/21/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Porter Federal 16-29, at Location # 335118 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Provide proof of tracking control BMP's

- Location shows signs of lack of stabilization BMP's in some areas (rutting is present) BMP's require maintenance.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	signage is located at tank battery		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Type	TANK BATTERY			
Comment:				
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	

Equipment:

				corrective date
Type: Plunger Lift	#			
Comment:				
Corrective Action:			Date:	
Type: Bradenhead	# 6			
Comment:	Braden heads have a port for manual gauge monitoring			
Corrective Action:			Date:	
Type: Gas Meter Run	# 6			
Comment:	All meters have been calibrated on location within the past year.			
Corrective Action:			Date:	
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors	# 9			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 6			
Comment:				
Corrective Action:			Date:	
Type: Ancillary equipment	# 2			
Comment:	chemical tanks at well heads			
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	200 BBLS	HEATED STEEL AST		,	
Comment:	Shared containment with 300 bbl tanks					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Ramsey, Scott

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	HEATED STEEL AST		,
Comment:	Shared containment with 200 bbl tank				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	260917	Type:	WELL	API Number:	045-07921	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	260919	Type:	WELL	API Number:	045-07923	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	285049	Type:	WELL	API Number:	045-12359	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	285050	Type:	WELL	API Number:	045-12360	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	285051	Type:	WELL	API Number:	045-12361	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	291190	Type:	WELL	API Number:	045-14317	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: tied into tank battery

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: Limited storm water inspection due to snow cover
 1. No evidence of tracking control BMP's
 2. Location shows signs of lack of stabilization BMP's in some areas (rutting is present)
 BMP's require maintenance.

Corrective Action: 1. Install, maintain or provide documentation of post construction management plan or BMP's
 2. Install or repair required BMPs in order to achieve stabilization on location

Date: 02/22/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402580792	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5335152
700702202	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5335146