

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2021

Submitted Date:

01/28/2021

Document Number:

696104259**FIELD INSPECTION FORM**Loc ID 306145 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285821	WELL	SI	10/01/2020	OW	123-24057	R. MILLER 13-24	SI

**General Comment:**[This is a WELL inspection.](#)[Well\(s\): 1: Shut-In | SI.](#)[Battery: Inactive | Shut-down.](#)[Centralized Battery serves 2 Location IDs \(306146, 306145\).](#)[\(Well\(s\): 2: Shut-In | SI\).](#)[Refer to Field Inspection Report doc. #696104257 and/or Location ID #306146  
for Battery / Facility, Equipment info.](#)

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type				
Comment:	Refer to Field Inspection Report doc. #696104257 and/or Location ID #306146 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No _____				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type				
Comment:	Refer to Field Inspection Report doc. #696104257 and/or Location ID #306146 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type:		#		corrective date
Comment:	Refer to Field Inspection Report doc. #696104257 and/or Location ID #306146 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type: Bradenhead		# 1		
Comment:	Appears plumbed to surface.			
Corrective Action:				Date:
Type: Plunger Lift		# 1		

Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.557764,-104.502211	
Comment:	<p>Centralized Battery serves 2 Location IDs (306146, 306145). (Well(s): 2: Shut-In   SI).</p> <p>Refer to Field Inspection Report doc. #696104257 and/or Location ID #306146 for Battery / Facility, Equipment info.</p>					
Corrective Action:					Date:	

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 285821 Type: WELL API Number: 123-24057 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment:

Shut-In | SI.  
Observed production valves shut.  
COGCC records indicate last production: 09/2020.

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment:

COGCC records indicate date of last Brhd Test: 09/14/2020.  
Database not displaying correct date.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On THU 01/28/2021 at approximately 13:21 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: PDC ENERGY INC  Location Name: R. MILLER-67N64W /24NWSW  Location ID: 306145  Well Name: R. Miller 13-24  API: 05-123-24057  Location County: Weld County, Colorado  Weather: Mostly cloudy, partial snow cover, damp from prior storm.</p> <p>While there, I observed:  Well(s): 1: Shut-In   SI.  Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (306146, 306145).  (Well(s): 2: Shut-In   SI).</p> <p>Refer to Field Inspection Report doc. #696104257 and/or Location ID #306146 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	01/28/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104260	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339689">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339689</a>