

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2021

Submitted Date:

01/29/2021

Document Number:

696104263**FIELD INSPECTION FORM**Loc ID 305806 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|---------------------------------|
| , | | cogccinspection@pdce.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 282467 | WELL | SI | 04/01/2020 | OW | 123-23507 | PAPPENHEIM 22-24 | SI |

General Comment:

This is a WELL inspection.
Well(s): 1: Shut-In | SI.
Battery: Inactive | Shut-down.

Centralized Battery serves 3 Location IDs (305808, 305806, 305807).
(Well(s): 3: Shut-In | SI).

Refer to Field Inspection Report doc. #696104261 and/or Location ID #305808
for Battery / Facility, Equipment info.

| Location | | | | |
|--|---|--------|--|-----------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | Adequate | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | WELLHEAD | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type | | | | |
| Comment: | Refer to Field Inspection Report doc. #696104261 and/or Location ID #305808 for Battery / Facility, Equipment info. | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: _____ |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | WELLHEAD | | | |
| Comment: | Iron panel. | | | |
| Corrective Action: | | | | Date: |
| Type | | | | |
| Comment: | Refer to Field Inspection Report doc. #696104261 and/or Location ID #305808 for Battery / Facility, Equipment info. | | | |
| Corrective Action: | | | | Date: |
| Equipment: | | | | |
| Type: Bradenhead | # 1 | | | corrective date |
| Comment: | Appears plumbed to surface. | | | |
| Corrective Action: | | | | Date: |
| Type: Plunger Lift | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: | # | | | |
| Comment: | Refer to Field Inspection Report doc. #696104261 and/or Location ID #305808 for Battery / Facility, Equipment info. | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Tanks and Berms:

| | | | | | | |
|--------------------|---|--|---------------------|---------|-----------------------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| | | | CENTRALIZED BATTERY | | 40.561213,-104.505428 | |
| Comment: | | Centralized Battery serves 3 Location IDs (305808, 305806, 305807). Refer to Field Inspection Report doc. #696104261 and/or Location ID #305808 for Battery / Facility, Equipment info. | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | | | | |
|------------------|--|--|--|--|--|
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected FacilitiesFacility ID: 282467 Type: WELL API Number: 123-23507 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Observed production valves shut.
COGCC records indicate last production: 03/2020.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: Annual Brhd Completed? #ErrorLast Brhd Test Results Initial Surf Csg Pressure: Fluid Type: End Surf Csg Pressure: Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary:</p> <p>On THU 01/28/2021 at approximately 14:06 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: PAPPENHEIM-67N64W /24SENW Location ID: 305806 Well Name: Pappenheim 22-24 API: 05-123-23507 Location County: Weld County, Colorado Weather: Mostly cloudy, partial snow cover, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 3 Location IDs (305808, 305806, 305807). (Well(s): 3: Shut-In SI).</p> <p>Refer to Field Inspection Report doc. #696104261 and/or Location ID #305808 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p> | evinsb | 01/29/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696104264 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5339691 |