



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type WELLHEAD

Comment: [Fabricated fencing](#)

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment #

Comment: [Automation](#)

Corrective Action:

Date:

Type: Bradenhead # 1

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 201938 Type: WELL API Number: 001-07342 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? #Error  
 Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: \_\_\_\_\_  
 Comment: Annual bradenhead test is not current. Contact COGCC engineering. 01/22/2021  
 Corrective Action: Comply with 341 c Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On 1/12/21 at approximately 1440I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Hosmer Harold W 2                      Company Name- KPK                      API- 05-001-07342                      In Adams County Colorado.                      While there, I observed Producing well                      During this inspection the following possible compliance issues were observed:                      Annual bradenhead test is not current. Contact COGCC engineering.                      Comply with 341 c 1/22/21                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      At time of inspection weather conditions were overcast, warm, recent snow.                      This is a summary of inspection report.</p>	medinaj	01/12/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402573351	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5328483">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5328483</a>
699502128	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5328476">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5328476</a>