

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/29/2021

Submitted Date:

02/01/2021

Document Number:

700702243

FIELD INSPECTION FORM

 Loc ID 420223 Inspector Name: Ramsey, Scott On-Site Inspection
 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 10447
 Name of Operator: URSA OPERATING COMPANY LLC
 Address: 950 17TH STREET, SUITE 1900
 City: DENVER State: CO Zip: 80202
Findings:

- 23 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420217	WELL	PR	08/29/2012	GW	045-20107	McLin C7	PR
420236	WELL	PR	08/29/2012	GW	045-20112	McLin C2	PR
420279	WELL	PR	03/03/2014	GW	045-20113	McLin C3	PR
420289	WELL	PR	03/30/2012	GW	045-20117	McLin C16	PR
420291	WELL	PR	03/03/2014	GW	045-20118	McLin C5	PR
420329	WELL	PR	10/29/2012	GW	045-20130	McLin C20	PR
420331	WELL	PR	08/29/2012	GW	045-20131	McLin C13	PR
420332	WELL	PR	11/30/2013	GW	045-20132	McLin C15	PR
420333	WELL	PR	08/29/2012	GW	045-20133	McLin C24	PR
420336	WELL	DG	10/08/2019	LO	045-20135	McLin C8	DG
420338	WELL	DG	10/08/2019	LO	045-20136	McLin C17	DG
420340	WELL	PR	08/29/2012	GW	045-20138	McLin C23	PR
420341	WELL	PR	10/29/2012	GW	045-20139	McLin C19	PR
420343	WELL	PR	10/29/2012	GW	045-20140	McLin C18	PR
420344	WELL	PR	08/29/2012	GW	045-20141	McLin C22	PR
420345	WELL	PR	11/30/2013	GW	045-20142	MCLIN C6	PR

General Comment:

COGCC Inspection Report Summary

On Friday 1/29/2021 at approximately 1300, I, Inspector Scott Ramsey, conducted a follow up inspection at Ursa Mclin C, at Location # 420223 in Garfield county Colorado.

While there, I observed normal production operations. All meters calibrated on location within a year. C/A's from previous inspection document # 700701912 have been completed.

During this inspection the following possible compliance issues were observed:

1. Tank battery signage is missing information and located at entrance
2. Location still shows signs of lack of stabilization from previous inspection

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	1. Tank battery signage is missing information and located at entrance		
Corrective Action:	Install sign in correct location and provide correct information		Date: 04/30/2021
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Deadman # & Marked	# 3		corrective date
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 14		
Comment:	Seven (7) braden heads are tied into sales and all Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 14		
Comment:	All meters calibrated on location within a year.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 14		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	chemical tank at well heads		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	one (1) tank is heated and all are in a shared containment with produced water tanks				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	300 BBLs	STEEL AST		,

Comment:	all are in a shared containment with condensate tanks	
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	420217	Type:	WELL	API Number:	045-20107	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	420236	Type:	WELL	API Number:	045-20112	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	420279	Type:	WELL	API Number:	045-20113	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	420289	Type:	WELL	API Number:	045-20117	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	420291	Type:	WELL	API Number:	045-20118	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	420329	Type:	WELL	API Number:	045-20130	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	420331	Type:	WELL	API Number:	045-20131	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	420332	Type:	WELL	API Number:	045-20132	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Facility ID: 420333	Type: WELL	API Number: 045-20133	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 420336	Type: WELL	API Number: 045-20135	Status: DG	Insp. Status: DG
Facility ID: 420338	Type: WELL	API Number: 045-20136	Status: DG	Insp. Status: DG
Facility ID: 420340	Type: WELL	API Number: 045-20138	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 420341	Type: WELL	API Number: 045-20139	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 420343	Type: WELL	API Number: 045-20140	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 420344	Type: WELL	API Number: 045-20141	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:
Facility ID: 420345	Type: WELL	API Number: 045-20142	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:				Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Limited storm water inspection due to snow cover](#)
[2. Location still shows signs of lack of stabilization from previous inspection](#)

Corrective Action: [Maintain BMP's](#)

Date: 12/18/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702248	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5341117