

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL /30-12 (PL30)

Location ID: 414077



Photo #2768 from entrance to location.



Photo #2769 from entrance to location.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL /30-12 (PL30)

Location ID: 414077



**Photo #2770 Multiple places with flow line exhaust heating insulation open ended and not capped.**



**Photo #2771 Multiple places with flow line exhaust heating insulation open ended and not capped.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL /30-12 (PL30)

Location ID: 414077



**Photo #2772 Multiple places with flow line exhaust heating insulation open ended and not capped.**