

Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL-67S95W /30SWNE

Location ID: 334657



Photo #2778 from entrance to location.



Photo #2779 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL-67S95W /30SWNE

Location ID: 334657



Photo #2783 Flow line exhaust heating insulation open ended and not capped.



Photo #2780 Drain valve on tank #82965 leaking.

Inspection Photos

Location Name: CAERUS PICEANCE LLC DAYBREAK FEDERAL-67S95W /30SWNE

Location ID: 334657



Photo #2781 Hole in tank containment.