

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/26/2021

Submitted Date:

01/26/2021

Document Number:

699802483

FIELD INSPECTION FORM

Loc ID 334626 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

- 21 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258716	WELL	PR	12/12/2000	GW	045-07650	KNIGHT PA 41-5	PR
280663	WELL	PR	10/17/2005	GW	045-11315	KNIGHT PA 512-4	PR
280716	WELL	PR	07/20/2006	GW	045-11325	KNIGHT PA 441-5	PR
280717	WELL	PR	10/18/2005	GW	045-11326	KNIGHT PA 641-5	PR
280719	WELL	PR	07/20/2006	GW	045-11327	KNIGHT PA 511-4	PR
280720	WELL	PR	07/20/2006	GW	045-11328	KNIGHT PA 12-4	PR
280721	WELL	PR	03/08/2007	GW	045-11329	KNIGHT PA 312-4	PR
280722	WELL	PR	07/20/2006	GW	045-11330	KNIGHT PA 341-5	PR
280723	WELL	PR	07/20/2006	GW	045-11331	KNIGHT PA 411-4	PR
280724	WELL	PR	07/20/2006	GW	045-11332	KNIGHT PA 412-4	PR
280725	WELL	PR	10/18/2005	GW	045-11333	KNIGHT PA 541-5	PR

General Comment:

[COGCC Inspection Report Summary](#)
On Tuesday 1/26/21 at approximately 14:30 hours, I, Inspector Corey De Paolo, Conducted, an on-site inspection at TEP ROCKY MOUNTAIN LLC KNIGHT-67S95W /5NENE, Location #334626 in Garfield County Colorado.
While there, I observed normal production operations.
During this inspection the following possible compliance issues were observed: Multiple wellheads signs weathered and not legible. See photo #2725 and #2726 with a corrective action date of 2/26/21.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Multiple wellheads signs weathered and not legible. See photo #2725 and #2726		
Corrective Action:	Operators will ensure that signs are well maintained and legible, and will replace damaged signs.	Date:	02/26/2021
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 11		
Comment:	No form of pressure monitoring located on braden heads. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 11		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Centralized containment				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	258716	Type:	WELL	API Number:	045-07650	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	280663	Type:	WELL	API Number:	045-11315	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	280716	Type:	WELL	API Number:	045-11325	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	280717	Type:	WELL	API Number:	045-11326	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	280719	Type:	WELL	API Number:	045-11327	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	280720	Type:	WELL	API Number:	045-11328	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	280721	Type:	WELL	API Number:	045-11329	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				
Facility ID:	280722	Type:	WELL	API Number:	045-11330	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing				Date:				
Corrective Action:					Date:				

Facility ID: <u>280723</u>	Type: <u>WELL</u>	API Number: <u>045-11331</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing</u>				
Corrective Action:		Date:		
Facility ID: <u>280724</u>	Type: <u>WELL</u>	API Number: <u>045-11332</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing</u>				
Corrective Action:		Date:		
Facility ID: <u>280725</u>	Type: <u>WELL</u>	API Number: <u>045-11333</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<u>Producing Well</u>				
Comment: <u>Producing</u>				
Corrective Action:		Date:		

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Ditches				
Berms						
Gravel						
		Berms				
		Compaction				
		Culverts				
		Gravel				

Comment: [Location covered with snow at the time of inspection.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402584248	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5337927
699802484	Photos for Insp. #699802483	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5337922