

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/02/2021

Submitted Date:

02/02/2021

Document Number:

699802529

**FIELD INSPECTION FORM**

Loc ID 334599 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

14 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerusoilandgas.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287313	WELL	PR	05/13/2007	GW	045-12963	SHORE 16-7 (PG16)	PR
288249	WELL	SI	08/01/2020	GW	045-13179	SHORE 16-6 (PG16)	SI
288250	WELL	PR	05/15/2007	GW	045-13178	SHORE 16-6BB(PG16)	PR
288251	WELL	PR	05/18/2007	GW	045-13177	SHORE 16-3 (PG16)	PR
288252	WELL	PR	05/24/2007	GW	045-13176	SHORE 16-3BB(PG16)	PR
288929	WELL	PR	05/26/2007	GW	045-13622	SHORE 16-7BB (PG16)	PR

**General Comment:**

[COGCC Inspection Report Summary](#)  
On Tuesday 2/2/21 at approximately 14:00 hours, I, Inspector Corey De Paolo, Conducted, an on-site inspection at CAERUS PICEANCE LLC SHORE-67S95W /16SWNE, Location #334599 in Garfield County Colorado.  
While there, I observed normal production operations.  
This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Summit midstream		
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:

Type: Bradenhead	# 6	
Comment:	Pressure transducers located on all braden heads. All braden head valves are accessible.	
Corrective Action:		Date:
Type: Gas Meter Run	# 6	
Comment:	All meter runs have been calibrated in the last year.	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 6	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 287313 Type: WELL API Number: 045-12963 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 288249 Type: WELL API Number: 045-13179 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last produced July 2020

Corrective Action:

Date: \_\_\_\_\_

Facility ID: 288250 Type: WELL API Number: 045-13178 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 288251 Type: WELL API Number: 045-13177 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 288252 Type: WELL API Number: 045-13176 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 288929 Type: WELL API Number: 045-13622 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						
		Berms				
Compaction						
Gravel						
		Gravel				
		Culverts				
		Sediment Traps				
Sediment Traps						
Ditches						
		Compaction				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699802530	Photos for Insp. #699802529	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5343695">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5343695</a>