

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/03/2021

Submitted Date:

02/03/2021

Document Number:

700702261

FIELD INSPECTION FORM
 Loc ID 335546 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10447

Name of Operator: URSA OPERATING COMPANY LLC

Address: 950 17TH STREET, SUITE 1900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292287	WELL	PR	09/17/2007	GW	045-14673	ROBINSON C 13	PR
292288	WELL	PR	09/07/2011	GW	045-14672	Robinson C4	PR
292289	WELL	PR	11/01/2020	GW	045-14671	ROBINSON C7	PR
292290	WELL	PR	09/18/2007	GW	045-14670	ROBINSON C14	PR
292291	WELL	PR	01/17/2012	GW	045-14669	Robinson C11	PR
292292	WELL	PR	01/17/2012	GW	045-14668	Robinson C9	PR
292293	WELL	PR	01/17/2012	GW	045-14667	Robinson C1	PR
298259	WELL	PR	06/22/2012	GW	045-17104	Robinson C12	PR
298260	WELL	PR	01/15/2013	GW	045-17105	Robinson C3	PR
298261	WELL	PR	06/26/2012	GW	045-17106	Robinson C6	PR
298262	WELL	PR	09/05/2011	OW	045-17107	Robinson C8	PR
298263	WELL	PR	06/26/2012	GW	045-17108	Robinson C2	PR
298264	WELL	PR	06/26/2012	GW	045-17109	Robinson C10	PR

General Comment:

COGCC Inspection Report Summary

On Wednesday 2/3/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a follow up inspection at Ursa Robinson C, at Location # 335546 in Garfield county Colorado.

While there, I observed normal production operations. All meters calibrated on location within a year. C/A's from previous inspection document # 700701962 have not been completed. Operator has provided documentation of their Best Management Practices for Pad Surface Stabilization.

During this inspection the following possible compliance issues were observed:

1. Tank battery signage is missing information and located at entrance
2. Location still shows signs of lack of stabilization from previous inspection
3. One dead man is unmarked

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	1. Tank battery signage is missing information and located at entrance		
Corrective Action:	Install sign in correct location and provide correct information	Date:	04/30/2021

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 1		corrective date
Comment:	chemical tank at well heads		

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 13		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	#		
Comment:	one dead man is unmarked		
Corrective Action:	mark or remove dead man	Date:	02/24/2021
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 13		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 13		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,
Comment:	one tank is heated				

Corrective Action:				Date:	
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type	Ignitor/Combustor				
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	292287	Type:	WELL	API Number:	045-14673	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	292288	Type:	WELL	API Number:	045-14672	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	292289	Type:	WELL	API Number:	045-14671	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	292290	Type:	WELL	API Number:	045-14670	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	292291	Type:	WELL	API Number:	045-14669	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	292292	Type:	WELL	API Number:	045-14668	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	292293	Type:	WELL	API Number:	045-14667	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	298259	Type:	WELL	API Number:	045-17104	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	298260	Type:	WELL	API Number:	045-17105	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	298261	Type:	WELL	API Number:	045-17106	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	298262	Type:	WELL	API Number:	045-17107	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	298263	Type:	WELL	API Number:	045-17108	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	298264	Type:	WELL	API Number:	045-17109	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: tied into tank burner

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 2. Location still shows signs of lack of stabilization

Corrective Action: maintain all BMP's

Date: 01/06/2021

Pits: ☒ NO SURFACE INDICATION OF PIT