



**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
	Comment: Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

	Type WELLHEAD		
	Comment: Panels		
Corrective Action:		Date:	

**Equipment:**

				corrective date
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:		Date:		
Type: Bradenhead	# 1			
Comment:	Appears to be plumbed to surface.			
Corrective Action:		Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 249226 Type: WELL API Number: 123-17028 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 448092 Type: TANK API Number: - Status: AC Insp. Status: AC

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On (2/3/21) at approximately (10:45 HRS), I, Inspector (Abe Serna),                      Conducted an on-site inspection at (Stroh 35-4) (Noble Energy), at                      (Location #329225) in (Weld County) Colorado.                      While there, I observed a (TA Well)                      During this inspection compliance issues were observed.                      No follow up on this site inspection needs to be conducted.                      This is a summary of inspection report.</p>	sernaa	02/03/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698702434	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5344470">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5344470</a>