

Inspection Photos

API: 061-06742

Operator: NEWELL ENERGY LTD

Inspection Date: 2/2/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06742 | Date: 2/2/2021

Inspection Photos



Photo 1. Facing east along the access road. The cattle guard is filled in with sediment and is not maintained. There is erosion occurring down the road shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 2/2/2021

Inspection Photos



Photo 2. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 2/2/2021

Inspection Photos



Photo 3. Unused pipe remains at the location. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 2/2/2021

Inspection Photos



Photo 4. Facing south toward the location. Unused areas of the location are bare of vegetation cover. Interim reclamation has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 2/2/2021

Inspection Photos




Photo 5. The fence panels at the well are laying on the ground. The location sign on the panels is not properly installed. There is unused equipment that remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 2/2/2021

Inspection Photos



Photo 6. Facing toward the tanks. Tank shown at red arrow is labeled produced water. Other tank contents are not labeled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 2/2/2021

Inspection Photos



Photo 7. Facing east near the tank. There is no vegetation growth downhill of the tanks indicating a possible spill occurred.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 2/2/2021

Inspection Photos



Photo 8. There is no vegetation growth downhill of the tanks indicating a possible spill occurred.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 2/2/2021

Inspection Photos



Photo 9. Facing west at the area which is bare of vegetation. It appears this area may have been impacted from a potential spill. This bare area extends 300 ft. downhill from the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 2/2/2021

Inspection Photos



Photo 10. Facing toward the tanks. The berm around the tanks is degraded and has holes in the side. The labeling is shown on the back side of the tank and needs to be posted where it is visible front the front side. Tank does not have contents labeled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 2/2/2021

Inspection Photos



Photo 11. Facing toward the front side of the tanks.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06742 | Date: 2/2/2021