

Inspection Photos
Operator: Simcoe
API: 067-09671
Date: 2/2/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with intermediate wheatgrass, western wheatgrass, smooth brome, and crested wheatgrass.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of musk thistles (approx. 200) observed along the access road. Approximately 500 Russian knapweeds also present along access (see inset)



Photo 5. View of the reference area comprised of open pasture, largely snow covered at this time.