

Inspection Photos

Location Name: CAERUS PICEANCE LLC Daybreak Federal /19-2 (PJ19)

Location ID: 417538



Photo #2813 from entrance to location.



Photo #2815 Multiple places with flow line exhaust heating insulation open ended and not capped.

Inspection Photos

Location Name: CAERUS PICEANCE LLC Daybreak Federal /19-2 (PJ19)

Location ID: 417538



Photo #2816 Multiple places with flow line exhaust heating insulation open ended and not capped.