

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/02/2021

Submitted Date:

02/05/2021

Document Number:

691201372

FIELD INSPECTION FORM

Loc ID 319582 Inspector Name: Graber, Candice (Nikki) On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		cogccinspection@pdce.com	
, Spills&Remediations		COGCCSpillRemediation@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243716	WELL	SI	01/01/2019	OW	123-11508	FIELDS-NELSON 34-1	EI

General Comment:

This is an environmental inspection in response to the Nelson 34-1 flowline spill (Document #402585057) reported by Operator on 1/26/2021.
Any corrective actions from previous inspections that have not been addressed are still applicable.

Location

Overall Good:

Emergency Contact Number:

Comment: Good

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type OTHER

Comment: Excavation fencing on location.

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 243716 Type: WELL API Number: 123-11508 Status: SI Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: At the time of inspection crews were continuing to delineate the extent of impacts. Groundwater was present in contact with impacted soils; field personnel advise that the excavation had been vac'd that morning to allow for additional excavation. Operator has submitted a Form 27 for Remediation 16548.

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
Oily Soil	Other	Adequate		
Comment	Trucks were being directly loaded from the excavation for offsite disposal; no oily waste was being stockpiled on location.			
Corrective Action				Date: _____

Spill/Remediation:

Comment: _____
 Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Wetlands to the north were being protected and a concise traffic pattern was being followed to protect the adjacent fallow agricultural fields](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691201373	Soil being loaded for offsite disposal	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5345544
691201374	Impacted soils in contact with groundwater	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5345545
691201375	Excavation with infiltrating groundwater	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5345546