

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2021

Submitted Date:

02/04/2021

Document Number:

693700693**FIELD INSPECTION FORM**Loc ID 444465 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96155Name of Operator: WHITING OIL & GAS CORPORATIONAddress: 1700 LINCOLN STREET SUITE 4700City: DENVER State: CO Zip: 80290**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|------------------------------|--|
| MacLaren, Joe | | joe.maclaren@state.co.us | |
| CO, Eastern | | WhitingEasternCO@Whiting.com | All Eastern CO Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------------------|--------|-------------|------------|---------|---------------|-------------|
| 479109 | SPILL OR RELEASE | AC | 01/21/2021 | | - | Razor 25O | EI |

General Comment:

Environmental**Spill/Remediation:**

Comment: COGCC Inspection of crude oil spill reported from flowline. Flowline has been exposed and shut-in, with free liquids removed. Failed section of pipe removed for inspection (photo). impacts remain in flowline trench requiring additional investigation and remediation. Operator to submit Form 19 Supplemental Report with final root cause and confirmation soil samples results demonstrating compliance with Table 915-1 for Form 27 Site Investigation and Remediation Workplan within 90 days of release discovery (April 8, 2021).

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 693700694 | Exposed flowline release point | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5345550 |