

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/29/2021

Submitted Date:

02/04/2021

Document Number:

693700705**FIELD INSPECTION FORM**Loc ID 441005 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478863	SPILL OR RELEASE	AC	01/08/2021		-	Pronghorn D-28 oil line	EI

General Comment:[COGCC Environmental Inspection of Spill ID 478863 Pronghorn D-28 oil line.](#)

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: Operator reported spill from oil line on PRonghorn D-28 wellpad near separator bank. From Form 19 "The failure was discovered on a span of pipe and located in the six o'clock position." Operator has removed separators and excavated impacted material around separator risers. Impacted material remains in place. Operator has indicated a plan to conducted further investigation via soil borings to determine the extent of the impacts. Operator will submit Form 19 with root cause and confirmation soil sample results documenting compliance with Table 915-1 or a Form 27 Site Investigation and Remediation Workplan within 90 days of release discovery (by March 18, 2021).

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700706	Excavation along separator risers	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5345558
693700707	Excavation along separator risers	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5345559