

Inspection Photos

API: 061-06866

Operator: NAVEX RESOURCES LLC

Inspection Date: 2/2/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06866 | Date: 2/2/2021

Inspection Photos



Photo 1. Facing east along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06866 | Date: 2/2/2021

Inspection Photos



Photo 2. Facing north at the center of the location. Vegetation has not established at the location. Soils are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06866 | Date: 2/2/2021

Inspection Photos




Photo 3. Facing west at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06866 | Date: 2/2/2021

Inspection Photos




Photo 4. Facing south at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06866 | Date: 2/2/2021

Inspection Photos



Photo 5. Facing west at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06866 | Date: 2/2/2021

Inspection Photos



Photo 6. Facing southwest. Vegetation has not established at the location. Soils are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06866 | Date: 2/2/2021

Inspection Photos



Photo 7. Facing north toward the surrounding undisturbed pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06866 | Date: 2/2/2021