

Inspection Photos

API: 061-06876

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 2/2/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing east at the beginning of the access road. The road has recently been reclaimed. Straw mulch was applied to the soil however, much of the straw has blown away in this area of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06876 | Date: 2/2/2021

Inspection Photos



Photo 2. Facing east along the reclaimed access road. Did not inspect past this point of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06876 | Date: 2/2/2021