

Inspection Photos

API: 011-06194

Operator: FOUNDATION ENERGY
MANAGEMENT

Inspection Date: 2/2/2021



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06194 | Date: 2/2/2021

Inspection Photos



Photo 1. Facing southeast toward the former access road. The two track road remains and will need to be decompacted and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06194 | Date: 2/2/2021

Inspection Photos



Photo 2. Facing north toward the location. There are areas that do not have vegetation. These areas will likely need to be decompacted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06194 | Date: 2/2/2021

Inspection Photos



Photo 3. Facing northwest toward the location. The bare areas will need to be decompacted and reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06194 | Date: 2/2/2021

Inspection Photos



Photo 4. Facing north at the east side of the location. This disturbance area will need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06194 | Date: 2/2/2021

Inspection Photos



Photo 5. Facing west at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06194 | Date: 2/2/2021

Inspection Photos



Photo 6. Facing west toward the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06194 | Date: 2/2/2021