

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/01/2021

Submitted Date:

02/05/2021

Document Number:

689805338**FIELD INSPECTION FORM**Loc ID 313296 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10673Name of Operator: GADECO LLCAddress: 7535 EAST HAMPDEN AVE STE 400City: DENVER State: CO Zip: 80231**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	303-850-7498	grynpetro@grynberg.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285000	WELL	SI	08/01/2019	GW	081-07313	HIAWATHA STATE 4-3	WK

General Comment:

[Routine FIU inspection.](#)

[PA occurring. Form 6 document number 402549325.](#)

Inspected Facilities

Facility ID: 285000 Type: WELL API Number: 081-07313 Status: SI Insp. Status: WK

Workover

Comment: PA occurring. Perfs shot at 12300-12900 and crew rigging up to cement first plug.

Corrective Action:

Date: _____