

**CAERUS PICEANCE LLC  
N. Parachute MF H17 696  
Location # 335825**



**Location shows signs of lack of stabilization  
BMP's in some areas (rutting is present)**

**CAERUS PICEANCE LLC  
N. Parachute MF H17 696  
Location # 335825**



**Perimeter ditch needs maintained.**

**Sediment build up in ditch**

**CAERUS PICEANCE LLC  
N. Parachute MF H17 696  
Location # 335825**



**Location shows signs of lack of stabilization  
BMP's in some areas (rutting is present)**

**Location shows signs of lack of stabilization  
BMP's in some areas (rutting is present)**

**CAERUS PICEANCE LLC**  
**N. Parachute MF H17 696**  
**Location # 335825**



**Drainage merging with road ditch is full of sediment.**



**Drainage merging with road ditch is full of sediment.**

**CAERUS PICEANCE LLC  
N. Parachute MF H17 696  
Location # 335825**



**No evidence of tracking control BMP's**

**No evidence of tracking control BMP's**

**CAERUS PICEANCE LLC  
N. Parachute MF H17 696  
Location # 335825**



**No evidence of tracking control BMP's**