

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/29/2021

Submitted Date:

01/29/2021

Document Number:

700702241

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 417777 _____ Ramsey, Scott _____ 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10447
 Name of Operator: URSA OPERATING COMPANY LLC
 Address: 950 17TH STREET, SUITE 1900
 City: DENVER State: CO Zip: 80202
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 21 Number of Comments
 2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417823	WELL	PR	01/17/2012	GW	045-19639	Frei A21	PR
417824	WELL	PR	01/17/2012	GW	045-19640	Frei A11	PR
417825	WELL	PR	01/24/2014	GW	045-19641	Frei A9	PR
417829	WELL	PR	10/28/2011	GW	045-19642	Frei A16	PR
419521	WELL	PR	06/11/2014	OW	045-19945	Frei A20	PR
419524	WELL	XX	04/02/2018	LO	045-19946	Frei A17	XX
419525	WELL	PR	09/24/2014	OW	045-19947	Frei A14	PR
419527	WELL	PR	07/21/2014	OW	045-19949	Frei A12	PR
419529	WELL	PR	06/15/2014	OW	045-19951	Frei A18	PR
419530	WELL	DG	10/07/2019	LO	045-19952	Frei A4	DG
419532	WELL	PR	06/24/2015	OW	045-19953	Frei A23	PR
419534	WELL	DG	06/08/2016	LO	045-19954	Frei A2	DG
419535	WELL	PR	06/08/2014	OW	045-19955	Frei A19	PR
419539	WELL	DG	10/07/2019	LO	045-19958	Frei A1	DG
419540	WELL	DG	10/07/2019	LO	045-19959	Frei A3	DG
419541	WELL	PR	06/22/2015	OW	045-19960	Frei A24	PR
419542	WELL	PR	09/24/2014	OW	045-19961	Frei A10	PR

General Comment:

COGCC Inspection Report Summary

On Friday 1/29/2021 at approximately 1030, I, Inspector Scott Ramsey, conducted a follow up inspection at Ursa Frie A, at Location # 417777 in Garfield county Colorado.

While there, I observed normal production operations. Some C/A's from previous inspection document # 700701909 have been completed.

During this inspection the following possible compliance issues were observed:

1. Tank battery signage is missing information and located at entrance
2. Location still shows signs of lack of stabilization

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	1. Tank battery signage is missing information and located at entrance		
Corrective Action:	Install sign in correct location and provide correct information		Date: 04/29/2021
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	portable chemical tank at well heads		

Corrective Action:		Date:	
Type: Gas Meter Run	# 12		
Comment:	All meters calibrated on location within a year.		
Corrective Action:		Date:	
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 12		
Comment:	Eight (8) braden heads are tied into sales and all Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 7		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLS	STEEL AST		,
Comment:	shared containment with condensate tanks				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,

Comment:	One (1) tank is heated and all are in shared containment with produced water tanks	
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	417823	Type:	WELL	API Number:	045-19639	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	417824	Type:	WELL	API Number:	045-19640	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	417825	Type:	WELL	API Number:	045-19641	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	417829	Type:	WELL	API Number:	045-19642	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	419521	Type:	WELL	API Number:	045-19945	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	419524	Type:	WELL	API Number:	045-19946	Status:	XX	Insp. Status:	XX
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	419525	Type:	WELL	API Number:	045-19947	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	419527	Type:	WELL	API Number:	045-19949	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	419529	Type:	WELL	API Number:	045-19951	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Producing Well			
Comment:	producing		
Corrective Action:		Date:	

Facility ID: 419530 Type: WELL API Number: 045-19952 Status: DG Insp. Status: DG

Facility ID: 419532 Type: WELL API Number: 045-19953 Status: PR Insp. Status: PR

Producing Well			
Comment:	producing		
Corrective Action:		Date:	

Facility ID: 419534 Type: WELL API Number: 045-19954 Status: DG Insp. Status: DG

Facility ID: 419535 Type: WELL API Number: 045-19955 Status: PR Insp. Status: PR

Producing Well			
Comment:	producing		
Corrective Action:		Date:	

Facility ID: 419539 Type: WELL API Number: 045-19958 Status: DG Insp. Status: DG

Facility ID: 419540 Type: WELL API Number: 045-19959 Status: DG Insp. Status: DG

Facility ID: 419541 Type: WELL API Number: 045-19960 Status: PR Insp. Status: PR

Producing Well			
Comment:	producing		
Corrective Action:		Date:	

Facility ID: 419542 Type: WELL API Number: 045-19961 Status: PR Insp. Status: PR

Producing Well			
Comment:	producing		
Corrective Action:		Date:	

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Limited storm water inspection due to snow cover](#)
[2. Location still shows signs of lack of stabilization on cut slope from previous inspection](#)

Corrective Action: [Maintain BMP's](#)
[C/A date remains the same from previous inspection due to C/A not completed from Document # 700701909](#)

Date: 12/18/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402587564	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5341120
700702246	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5341115