

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/01/2021

Submitted Date:

02/01/2021

Document Number:

700702249**FIELD INSPECTION FORM**

Loc ID 421223	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 13 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>10447</u> Name of Operator: <u>URSA OPERATING COMPANY LLC</u> Address: <u>950 17TH STREET, SUITE 1900</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421260	WELL	XX	06/03/2016	LO	045-20334	McLin A 33D-12-06-92	XX
421261	WELL	XX	06/03/2016	LO	045-20335	McLin A 33B-12-06-92	XX
421262	WELL	XX	06/03/2016	LO	045-20336	McLin A 34A-12-06-92	XX
421263	WELL	XX	06/03/2016	LO	045-20337	McLin A 33A-12-06-92	XX
421264	WELL	PR	12/27/2014	OW	045-20338	McLin A 13B-12-06-92	PR
421265	WELL	XX	06/02/2016	LO	045-20339	McLin A 22C-12-06-92	XX
421266	WELL	PR	01/05/2015	OW	045-20340	McLin A 34C-12-06-92	PR
421268	WELL	XX	06/03/2016	LO	045-20342	McLin A 33C-12-06-92	XX
421269	WELL	XX	06/02/2016	LO	045-20343	McLin A 13A-12-06-92	XX
421270	WELL	XX	06/02/2016	LO	045-20344	McLin A 23A-12-06-92	XX
421271	WELL	XX	06/02/2016	LO	045-20345	McLin A 23C-12-06-92	XX
421272	WELL	PR	01/05/2015	OW	045-20346	McLin A 23D-12-06-92	PR
421273	WELL	XX	06/02/2016	LO	045-20347	McLin A 23B-12-06-92	XX
421274	WELL	PR	06/15/2016	OW	045-20348	McLin A 34D-12-06-92	PR
421275	WELL	PR	01/18/2015	OW	045-20349	McLin A 34B-12-06-92	PR

**General Comment:**

COGCC Inspection Report Summary

On Friday 2/1/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a follow up inspection at Ursa McIn A, at Location # 421223 in Garfield county Colorado.

While there, I observed normal production operations. All meters calibrated on location within a year. C/A's from previous inspection document # 700701910 have been completed.

During this inspection the following possible compliance issues were observed:

1. Tank battery signage is missing information and located at entrance
2. One (1) 55 gallon drum needs proper labeling

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	CONTAINERS			
Comment:	2. One (1) 55 gallon drum needs proper labeling			
Corrective Action:	install proper labeling			Date: 03/01/2021
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:	1. Tank battery signage is missing information and located at entrance			
Corrective Action:	Install sign in correct location and provide correct information			Date: 04/30/2021
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:				
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Vertical Heated Separator	# 8			corrective date
Comment:				

Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Braden heads have telemetry for monitoring.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:	All meters calibrated on location within a year.		
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 9		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	one (1) chemical tank at well heads. One (1) 500 gallon oil tank, Two (2) 55 gallon drums and one (1) used oil tote at compressor		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	Ignitor/Combustor		
Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID:	421260	Type:	WELL	API Number: 045-20334 Status: XX Insp. Status: XX
Facility ID:	421261	Type:	WELL	API Number: 045-20335 Status: XX Insp. Status: XX
Facility ID:	421262	Type:	WELL	API Number: 045-20336 Status: XX Insp. Status: XX
Facility ID:	421263	Type:	WELL	API Number: 045-20337 Status: XX Insp. Status: XX
Facility ID:	421264	Type:	WELL	API Number: 045-20338 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	421265	Type:	WELL	API Number: 045-20339 Status: XX Insp. Status: XX
Facility ID:	421266	Type:	WELL	API Number: 045-20340 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	421268	Type:	WELL	API Number: 045-20342 Status: XX Insp. Status: XX
Facility ID:	421269	Type:	WELL	API Number: 045-20343 Status: XX Insp. Status: XX
Facility ID:	421270	Type:	WELL	API Number: 045-20344 Status: XX Insp. Status: XX
Facility ID:	421271	Type:	WELL	API Number: 045-20345 Status: XX Insp. Status: XX
Facility ID:	421272	Type:	WELL	API Number: 045-20346 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	producing			
Corrective Action:				Date:
Facility ID:	421273	Type:	WELL	API Number: 045-20347 Status: XX Insp. Status: XX
Facility ID:	421274	Type:	WELL	API Number: 045-20348 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	producing			

Corrective Action:		Date:	
Facility ID: 421275    Type: WELL    API Number: 045-20349    Status: PR    Insp. Status: PR			
Producing Well			
Comment:	producing		
Corrective Action:		Date:	

## Environmental

### Spill/Remediation:

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): YES

Comment: tied into tank battery

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Operator has provided documentation of their Best Management Practices for Pad Surface Stabilization.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402588535	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5342000">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5342000</a>
700702252	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5341997">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5341997</a>