

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAMOND ELK-66S95W /36SWSE

Location ID: 335029



Photo #2820 from entrance to location.



Photo #2821 Rutting present on location due to lack of stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAMOND ELK-66S95W /36SWSE

Location ID: 335029



Photo #2822 Rutting present on location due to lack of stabilization.



Photo #2823 Ditch has been diverted due to rutting.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAMOND ELK-66S95W /36SWSE

Location ID: 335029



Photo #2824 Ditch has been diverted due to rutting.



Photo #2825 Ditch has been diverted due to rutting.