

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/01/2021

Submitted Date:

02/02/2021

Document Number:

699802521

FIELD INSPECTION FORM

Loc ID: 334752 Inspector Name: De Paolo, Corey On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 19 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277791	WELL	PR	07/12/2012	GW	045-10774	FEDERAL 30-3BB (PD30)	PR
277792	WELL	SI	08/01/2020	GW	045-10773	FEDERAL 30-5BB (PD30)	SI
277794	WELL	PR	01/26/2012	GW	045-10771	FEDERAL 30-5(PD30)	PR
277795	WELL	PR	01/26/2012	GW	045-10770	FEDERAL 30-3(PD30)	PR
278495	WELL	PR	02/02/2012	GW	045-10884	FEDERAL 30-4(PD30)	PR
278496	WELL	PR	08/01/2020	GW	045-10883	FEDERAL 30-4BB (PD30)	PR
412494	WELL	PR	01/26/2012	GW	045-18462	FEDERAL 19-14BB (PD30)	PR

General Comment:

[COGCC Inspection Report Summary](#)

On Monday 2/1/21 at approximately 13:30 hours, I, Inspector Corey De Paolo, Conducted, an on-site inspection at CAERUS PICEANCE LLC FEDERAL-67S95W /30NWNW, Location #334752 in Garfield County Colorado.

While there, I observed normal production operations. I contacted Caerus and informed them of the leak.

During this inspection the following possible compliance issues were observed: Flow line exhaust heating insulation open ended and not capped. See photo #2783 with a corrective action date of 3/1/21. Drain valve on tank #82965 leaking. See photo #2780 with a corrective action date of 2/3/21. Hole in tank containment. See photo #2781 with a corrective action date 3/11/21.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 7		
Comment:			

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Drain valve on tank #82965 leaking. See photo #2780		
Corrective Action:	All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened.		Date: 02/03/2021
Type: Gas Meter Run	# 1		
Comment:	Summit midstream		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks by wellheads		
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:	Pressure transducers located on all braden heads. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 7		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Flow line exhaust heating insulation open ended and not capped. See photo #2783		
Corrective Action:	Operators will prevent and minimize adverse impacts to wildlife resources.		Date: 03/01/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Hole in tank containment. See photo #2781			

Corrective Action:	The liner will be sufficiently impervious. Repair hole in tank containmment liner.	Date:	03/11/2021
--------------------	--	-------	------------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 277791 Type: WELL API Number: 045-10774 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 277792 Type: WELL API Number: 045-10773 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder: _____

Comment: Last produced July 2020

Corrective Action:

Date: _____

Facility ID: 277794 Type: WELL API Number: 045-10771 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 277795 Type: WELL API Number: 045-10770 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 278495 Type: WELL API Number: 045-10884 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 278496 Type: WELL API Number: 045-10883 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID: 412494 Type: WELL API Number: 045-18462 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps				
		Ditches				
		Culverts				
Sediment Traps						
Ditches						
		Check Dams				
		Berms				
Gravel						
Berms						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402589265	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5342842
699802523	Photos for Insp. #699802521	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5342837