

Inspection Photos

Location Name: CAERUS PICEANCE LLC NOCKS-68S96W /2NENE

Location ID: 334078



Photo #2838 from entrance to location.



Photo #2839 Front of berm. Sediment has been transported off of location due to snow plowing.

Inspection Photos

Location Name: CAERUS PICEANCE LLC NOCKS-68S96W /2NENE

Location ID: 334078



Photo #2840 Back side of berm Sediment has been push over berm.



Photo #2841 Back side of berm. Sediment has been push over berm.

Inspection Photos

Location Name: CAERUS PICEANCE LLC NOCKS-68S96W /2NENE

Location ID: 334078



Photo #2842 No BMP's in place to prevent the transportation of sediment from location.



Photo #2843 Pipe line right away.