

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/02/2021

Submitted Date:

02/02/2021

Document Number:

695103936**FIELD INSPECTION FORM**Loc ID 308693 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 6295 GREENWOOD PLAZA BLVD #100City: GREENWOOD State: CO Zip: 8111-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fitzgerald, Edie	719-859-1394	efitzgerald@ogrisop.com	All Inspections
Mack, Ronald		rmack@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279154	WELL	PR	07/01/2012	GW	071-08469	NEW ELK 35-01	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Phone 5: AREA OF IMPACTED SOIL ALL AROUND COMPRESSOR SKID APPEARS TO BE USED MOTOR/HYDRALIC OIL LEAKING FROM EQUIPMENT. Phone 6: AREA OF IMPACTED SOIL ALL AROUND COMPRESSOR SKID APPEARS TO BE USED MOTOR/HYDRALIC OIL LEAKING FROM EQUIPMENT.		
Corrective Action:	COMPLY WITH RULE 606 AND 608.e.	Date:	05/02/2021
Type	UNUSED EQUIPMENT		
Comment:	Phone 3: UNUSED EQUIPMENT STORED ON LOCATION (PRIME MOVER ENGINE SKID & DRIVEHEAD). Phone 4: UNUSED EQUIPMENT STORED ON LOCATION (DOWNHOLE PUMP AND POLISH ROD).		
Corrective Action:	COMPLY WITH RULE 606, REMOVE UNUSED EQUIPMENT.	Date:	05/02/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Vertical Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		

Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 279154 Type: WELL API Number: 071-08469 Status: PR Insp. Status: PR

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: WELL APPEARS TO BE SHUT IN AT TIME OF INSPECTION.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: [Phone 7: APPEAR THAT COMPRESSOR SKID IS FILLED WITH USED MOTOR OIL OR HYDRAULIC OIL.](#)

Corrective Action: [COMPLY WITH RULE 1002.f. AND Comply with general provisions of the oil and gas act for wildlife protection. AND SB-181.](#)

Date: 02/09/2021

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402589846	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5343443
695103937	INSP PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5343436