

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/09/2021

Submitted Date:

02/09/2021

Document Number:

701002357

FIELD INSPECTION FORM

Loc ID 466335 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 55098
Name of Operator: MCCOY PETROLEUM CORPORATION
Address: 9342 E CENTRAL AVE
City: WICHITA State: KS Zip: 67206-

Findings:

- 18 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Reinhardt, Brent	(316) 425-2339	brent@mccoypetroleum.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
466337	WELL	PR	03/11/2020	OW	017-07811	ALC 1447 1-23	PR

General Comment:

[Routine Inspection](#)

Location			
Lease Road:			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Lease sign by tanks		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on production tanks		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Stickers on chemical tank and propane tank		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Pipe fence barrier for ECD piping from tank battery to treater		
Corrective Action:		Date:	
Equipment:			
Type: Flare	# 1		corrective date
Comment:	Tall tan 48" flare on south side of ECD. Flare appears to be flaring gas from production side of treater		
Corrective Action:	Submit form 4 Sundry notice to flare produced gas	Date:	02/22/2021
Type: Vertical Heater Treater	# 1		
Comment:	Treater south of tanks on east side of ECDs		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	American 228		
Corrective Action:		Date:	

Type: Ancillary equipment	# 3		
Comment:	Propane tank, solar powered telemetry equipment, chemical drum w/containment		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	Black 48" ECD on south side of tank battery		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Arrow gas engine		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		38.821700,-102.636610
Comment:	South tank is water tank				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		38.821700,-102.636610
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	PVC Lined steel containment			
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 466337 Type: WELL API Number: 017-07811 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Reserve Lined: _____ Pit ID: _____ Lat: 38.821550 Long: -102.635660

Reference Point: SE Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Pit has been backfilled and compacted

Corrective Action Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action Date: _____

Type: Water Fresh Lined: _____ Pit ID: _____ Lat: 38.821930 Long: -102.635820

Reference Point: SE Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Pit has been backfilled and compacted

Corrective Action Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action Date: _____

Netting:

Netting Type:	Netting Condition:	
Comment:	<input type="text"/>	
Corrective Action	<input type="text"/>	Date:
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:
Comment:	<input type="text"/>	
Corrective Action	<input type="text"/>	Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701002363	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5349835