

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/03/2021

Submitted Date:

02/04/2021

Document Number:

688309648**FIELD INSPECTION FORM**Loc ID 316944 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10330Name of Operator: INVESTMENT EQUIPMENT LLCAddress: 412 W PLATTE AVECity: FT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Highberger, Kathryn	(970) 867-9007	kathrynhighberger@gmail.com	Designated Agent
Young, Rob		rob.young@state.co.us	COGCC EPS
Chisholm, Jim	405-642-9437	investmentequipment@gmail.com	All Inspections
Crumley, Luke	(970) 324-0060	crumleypumping@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
233377	WELL	PR	11/06/1963	OW	121-05413	DAVIS W T 1	PR

General Comment:

Reinspection, passed

Installed stormwater BMP on east end of pit to prevent off location sediment transport.

Inspected Facilities				
Facility ID: 233377	Type: WELL	API Number: 121-05413	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					

Comment: Erosion rill on east side of pit.Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C.Date: 02/22/2021**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: Other: Length: Width:

Lining:

Liner Type: Liner Condition:

Comment:

Corrective

Date:

Fencing:Fencing Type: None Fencing Condition:

Comment:

Corrective

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective

Date:

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Comment: Recent work on pit berms on north and south sides and below east pit (see attached photos). Check if stained soils in photos are oil stained soils and remove and properly dispose of if so.

Corrective

Date:

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: Other: Length: Width:

Lining:

Liner Type: Liner Condition:

Comment:

Corrective

Date:

Fencing:Fencing Type: None Fencing Condition:

Comment:

Corrective

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Inspector Name: Sherman, Susan

Corrective		Date:
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:
Comment:	west pit, deminimus oil in boom, remove oil	
Corrective		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402592193	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5345436
688309662	Investment Equipment Davis W T 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5345434