

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/11/2021

Submitted Date:

02/11/2021

Document Number:

699802587**FIELD INSPECTION FORM**Loc ID 311553 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard		g.richard.murray@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

General Comment:**COGCC Inspection Report Summary**

On Wednesday 2/10/21 at approximately 13:30 hours, I, Inspector Corey De Paolo, Conducted, a domestic tap inspection at TEP ROCKY MOUNTAIN LLC Domestic Tap /1NWNW, Location #456901 in Garfield County Colorado.

While there, I observed normal production operations.

The domestic tap is derived from the W-37-1 separator sales line. See photo #2879. The W-37-1 sales line is separate from location #335032 sale line. See photo # 2880. The W-37-1 sales line follows the access road to the base of the hill where the domestic tap stubs out of the ground. See photo #2881. The pressure is regulated by a Big Joe pressure regulator. Downstream of the regulator is a knock out bottle see photo #2882. After the knock bottle the domestic tap splits in to multiple taps. See photo #2883. One domestic tap services the house directly to the West of where the domestic tap stubs out of the ground.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Pipe rail fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699802588	Photos for Insp. #699802587	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5350092