

Inspection Photos

API: 043-06219

Operator: AUSCO PETROLEUM INC

Inspection Date: 2/9/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-06219 | Date: 2/9/2021

Inspection Photos



Photo 1. Facing northeast toward the location. Unused equipment has not been removed and interim reclamation has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 2/9/2021

Inspection Photos



Photo 2. Facing east at the location. There is 5 frac tanks staged that remain. The tanks have not been removed since previous inspection. Previous corrective actions have not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 2/9/2021

Inspection Photos



Photo 3. Facing north at the location. There is erosion occurring of the disturbed pad site which is filling in the perimeter wattles. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 2/9/2021

Inspection Photos



Photo 4. Facing southwest behind the frac tanks. The wattles have filled in with sediment. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 2/9/2021

Inspection Photos



Photo 5. Facing north at the location. Disturbed areas around the location have not been reclaimed and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 2/9/2021

Inspection Photos



Photo 6. The tanks at north side of the location are not properly labeled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 2/9/2021

Inspection Photos



Photo 7. Facing southeast at the location and toward the production equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 2/9/2021

Inspection Photos



Photo 8. Facing southwest toward the topsoil pile which are not maintained and protected from degradation and weed infestation. Previous corrective action has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 2/9/2021

Inspection Photos



Photo 9. Facing toward the topsoil pile. The topsoil piles are not stabilized and protected. Topsoil piles have not been replaced for interim reclamation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 2/9/2021

Inspection Photos



Photo 10. Facing northeast toward the location. The unused tanks need to be removed. This area needs to be recontoured and reclaimed. Previous corrective actions have not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06219 | Date: 2/9/2021