

# Inspection Photos

2/8/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 323856

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 323856



**Photo 1:** Photo taken from the entrance/gate on the northwest end of the Location, facing east. Photos 1-3 provide an overview of the Location from east, southeast to south.





## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 323856



**Photo 2:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 323856



**Photo 3:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 323856



**Photo 4:** Photo shows drop-down gate at the Location entrance is in disrepair.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 323856



**Photo 5:** Photo shows straw wattle BMP along southwestern perimeter of the Location is in disrepair. Additionally, wattle BMPs do not appear to have been installed in accordance with good engineering practices.





## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 323856



**Photo 6:** Photo shows hydro mulch has been applied to the soil surface of the reclamation area.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 323856



**Photo 7:** Photo taken from the west end of the Location. Photo shows pipe debris remaining. Photo also shows example of ripping marks on the Location. Rule 1004.a requires cross-ripping to a minimum depth of 18 inches; Location appears to have only been ripped in one direction (yellow lines); No indication that areas were cross ripped.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 323856



**Photo 8:** Photo shows areas of fence along the east end of the Location where strands appear to have been stretched or broken. Maintenance advised.

