

# Inspection Photos

2/8/2021

Operator: CHEVRON USA INC #16700

Location ID: 382974

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: CHEVRON USA INC #16700  
Location ID: 382974



**Photo 1:** Photo taken from the former location/access road entrance on the northeast end of the Location, facing west. Photo shows wattle BMPs at the access road.





Inspection Photos  
Operator Name: CHEVRON USA INC #16700  
Location ID: 382974



**Photo 2:** Continued from photo 1. Photo shows wattle BMPs on the Location remain improperly installed / not installed in accordance with good engineering practices. BMPs to stabilize the soils have not been installed and remain missing, or insufficient/inadequate.





Inspection Photos  
Operator Name: CHEVRON USA INC #16700  
Location ID: 382974



**Photo 3:** Continued from photo 1. Photo shows wattle BMPs on the Location remain improperly installed / not installed in accordance with good engineering practices. BMPs to stabilize the soils have not been installed and remain missing, or insufficient/inadequate.





Inspection Photos  
Operator Name: CHEVRON USA INC #16700  
Location ID: 382974



**Photo 4:** Photo taken from the northeast end of the Location, facing southwest. Photo provides an overview of the Location.



Inspection Photos  
Operator Name: CHEVRON USA INC #16700  
Location ID: 382974



**Photo 5:** Photo shows straw wattle BMP on the Location. Photo shows wattle BMPs on the Location remain improperly installed / not installed in accordance with good engineering practices.





Inspection Photos  
Operator Name: CHEVRON USA INC #16700  
Location ID: 382974



**Photo 6:** Photo shows straw wattle BMP on the Location. Photo shows wattle BMPs on the Location remain improperly installed / not installed in accordance with good engineering practices; Stormwater cutting beneath BMP. BMPs to stabilize the soils have not been installed and remain missing, or insufficient/inadequate.





Inspection Photos  
Operator Name: CHEVRON USA INC #16700  
Location ID: 382974



**Photo 7:** Photo shows straw wattle BMP on the Location. Photo shows wattle BMPs on the Location remain improperly installed / not installed in accordance with good engineering practices.





Inspection Photos  
Operator Name: CHEVRON USA INC #16700  
Location ID: 382974



**Photo 8:** Photo shows straw wattle BMP on the Location. Photo shows wattle BMPs on the Location remain improperly installed / not installed in accordance with good engineering practices. BMPs to stabilize the soils have not been installed and remain missing, or insufficient/inadequate.

