

**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location ID: 435733**



**Location shows signs of lack of stabilization BMP's  
in some areas (rutting is present).**

**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location ID: 435733**



**Access road shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**

**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location ID: 435733**



**Storm water not draining to culvert at  
entrance of location.**

**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location ID: 435733**



**Location shows signs of lack of stabilization BMP's  
in some areas (rutting is present).**

**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location ID: 435733**



**Access road shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**

**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location ID: 435733**



**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location ID: 435733**



**Access road shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**

**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location ID: 435733**



**Access road shows signs of lack of stabilization  
BMP's in some areas (rutting is present).**

**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location ID: 435733**



**Culvert basin needs maintained.**

**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location ID: 435733**



**Water not draining off road.**



**N39.55348 W-108.11985 Sediment build up in culvert outlet. Erosion damage from culvert outlet**

**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location ID: 435733**



**N39.55348 W-108.11985 Erosion damage from  
culvert outlet.**



**Erosion has exposed pipe line.**

**CAERUS PICEANCE LLC**  
**Chevron 42-5D**  
**Location ID: 435733**

