

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/04/2021

Submitted Date:

02/05/2021

Document Number:

696302921**FIELD INSPECTION FORM**Loc ID 427041 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10503Name of Operator: RED HAWK PETROLEUM LLCAddress: 575 N DAIRY ASHFORD STE 201City: HOUSTON State: TX Zip: 77079**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Allison, Rick		rick.allison@state.co.us	
Boyd, William		wboyd@pedevco.com	All Inspections
Kraich, Adam		adam.kraich@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427019	WELL	PR	08/01/2018	OW	123-34825	Buchner 1-2H	PR

General Comment:

This is a Field Inspection. Any Corrective Actions from Environmental Inspection #693700597 that have NOT Been addressed are STILL applicable with Original Corrective Action Dates.

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained Soil and Mechanical at Gas Engine, See photos		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. Cleanup Soil around Pumpjack Gas Engine	Date:	02/06/2021
Type	DEBRIS		
Comment:	Debris in Secondary Containment at Pumping Unit, see photo Wildlife Netting missing on Secondary Containment, see photo		
Corrective Action:	Remove Trash and Debris from Containment and Install Wildlife Netting.	Date:	02/12/2021
Type	OTHER		
Comment:	Loadline Buckets at Tank Battery - Oily Waste in buckets and Lids missing; wildlife hazard. See photos		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. Cleanup Soil around Loadline Buckets.	Date:	02/06/2021
Type	OTHER		
Comment:	Stained Soil and Mechanical Conditions at Wellhead, see photos		
Corrective Action:	For localized stained soils or oily waste - Properly dispose of oily waste in accordance Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition	Date:	02/07/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	
Crude Oil		<= 1 bbl	
Comment:	Standing Oil at Flare and ECD. See photos		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. Cleanup Soil around Flare and ECD.	Date:	02/06/2021
Crude Oil	Treater	<= 1 bbl	

Comment:	Leaking Gasket on Treater with small amount of oil impacting road base within Treater Containment STILL REMAINS. See photos			
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. Cleanup impacted material around base of treater and handle		Date:	10/23/2020

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Flare	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with the Crude Oil Tanks				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLs	STEEL AST		40.603210,-104.067003
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type	Field Flare				
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	427019	Type:	WELL	API Number:	123-34825	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>This is a Field Inspection, any Corrective Action(s) from Previous Environmental Inspection 693700597 dated 09.24.2020 that have not been addressed are still applicable.</p> <p>COGCC Inspection Report Summary</p> <p>On Wednesday 02/03/2021 at approximately 11:55, I, Inspector Erica Petrie, conducted a Field Inspection at Red Hawk Petroleum LLC , Buchner 1-2H, Location #427041 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Leaking Gasket on Treater with small amount of oil impacting road base within Treater Containment STILL REMAINS. See photos</p> <p>Standing Oil at Flare and ECD. See photos</p> <p>Stained Soil and Mechanical Conditions at Wellhead, see photos</p> <p>Stained Soil and Mechanical at Gas Engine, See photos</p> <p>Loadline Buckets at Tank Battery - Oily Waste in buckets and Lids missing; wildlife hazard. See photos</p> <p>Debris in Secondary Containment at Pumping Unit, Wildlife Netting missing on Secondary Containment, see photo</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report.</p>	petrie	02/05/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402592774	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5345990
696302922	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5345988