

Inspection Photos

2/8/2021

Operator: CHEVRON USA INC #16700

Location ID: 323798

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location ID: 323798



Photo 2: Continued from photo 1. Photo also shows utility equipment remaining on the Location.



Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location ID: 323798



Photo 3: Photo taken from the west end of the Location, facing north. Photos 3-5 provide an overview of the Location from north, east to southeast. Photos show final reclamation (including, but not limited to, removal of equipment/debris, recontouring/regrading, compaction alleviation and revegetation activities) has not been conducted in accordance with 1004 Rules.



Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location ID: 323798



Photo 4: See comments under photo 3.

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location ID: 323798



Photo 5: See comments under photo 3.

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location ID: 323798



Photo 6: Photo shows shed/equipment remaining on the north end of the Location.

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location ID: 323798



Photo 7: Photo taken from the east end of the Location. Photo shows fence equipment and concrete blocks remaining on the Location.

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location ID: 323798



Photo 8: Photo taken from the east end of the Location, facing east. Photo shows various debris or equipment remaining on the Location.

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location ID: 323798



Photo 9: Photo taken from the east end of the Location, facing northeast. Photo shows various debris or equipment remaining on the Location. Photo also shows soil stockpile on the northeast corner of the Location.

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location ID: 323798



20210208

Photo 10: Photo taken from the southeast end of the Location, facing northwest. Photos 10-12 provide an overview of the Location from northwest, north to northeast. Photos show final reclamation (including, but not limited to, removal of equipment/debris, recontouring/regrading, compaction alleviation and revegetation activities) has not been conducted in accordance with 1004 Rules.

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location ID: 323798



Photo 11: See comments under photo 10. Photo also shows cut-slopes of the Location and equipment remaining. .

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location ID: 323798



Photo 12: See comments under photo 10.

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location ID: 323798



Photo 13: Photo taken from the Location entrance on the northwest end of the site, facing northwest. Photo shows access road has not been recontoured/regraded and reclaimed.

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location ID: 323798



Photo 14: Photo taken from the access road entrance, northwest of the Location, facing southeast. Photo shows access road has not been recontoured/regraded and reclaimed.

Inspection Photos
Operator Name: CHEVRON USA INC #16700
Location ID: 323798



Photo 15: 2019 Google Earth Aerial image. Photo shows overview of the Location. Well PA 11/4/2013, Final Reclamation activities pursuant to Rule 1004.a was required by 11/4/2014.