

Inspection Photos
Operator: Catamount
API: 067-05332
Date: 2/8/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Revegetation is progressing, largely with western wheatgrass.



Photo 3. View of the northern project area facing westward.



Photo 4. View of the reference area comprised of sagebrush shrubland with understory of grasses and forbs such as western wheatgrass, sand dropseed, and James galleta.