

Inspection Photos
Operator: Logos
API: 067-05297
Date: 2/8/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing, largely with western wheatgrass. Dense kochia observed along the eastern edge of the working area.



Photo 3. View of kochia debris stuck around wellhead.



Photo 4. View of the reference area comprised of sagebrush shrubland with understory of grasses and forbs such as western wheatgrass, sand dropseed, and James galleta.