

Inspection Photos

Operator: Logos

API: 067-06249

Date: 2/8/2021



Photo 1. View of the project area from the southwestern corner facing center. Vegetation on the well pad is in a grazed/dormant condition.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is conducted. Slopes are tracked. Mulching is not present. Revegetation needs to be monitored. Cattle exclusion is recommended.



Photo 3. View of the northern cut slope from the northwestern corner facing eastward.




Photo 4. View of closed gate after leaving location.



Photo 5. View of the reference area comprised of sagebrush shrubland with understory of grasses and forbs such as western wheatgrass, sand dropseed, and James galleta.