



40.07193, -108.77118, 5239.5ft, 298°  
02/04/2021 11:38:59 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Pump jack.**

**Tranco 5A     API: 05-103-05320**  
**Inspection: 700405325**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Well with gas leak.**

**Tranco 5A     API: 05-103-05320**  
**Inspection: 700405325**





40.07197, -108.77125, 5199.5ft, 287°  
02/04/2021 11:46:27 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Tanks.**

Tranco 5A      API: 05-103-05320  
Inspection: 700405325