

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/09/2021

Submitted Date:

02/12/2021

Document Number:

700702286

FIELD INSPECTION FORMLoc ID 334629 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283775	WELL	PR	05/17/2006	GW	045-11993	CIRCLE B LAND 23B-35-692	PR
283989	WELL	PR	09/09/2006	GW	045-12059	CIRCLE B LAND 13C-35-692	PR
283990	WELL	PR	06/23/2006	GW	045-12064	CIRCLE B LAND 13A-35-692	PR
283992	WELL	PR	06/23/2006	GW	045-12063	CIRCLE B LAND 23D-35-692	PR
284741	WELL	PR	06/23/2006	GW	045-12259	CIRCLE B LAND 22A-35-692	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 2/9/2021 at approximately 1300, I, Inspector Scott Ramsey, conducted a follow up inspection at Grizzly Circle B 3, at Location # 334629 in Garfield county Colorado.

While there, I observed normal production operations. All meters calibrated on location within a year. Some of the C/A's from previous inspection document # 700702024 have NOT been completed. This location is within a Density Habitat and Wildlife Management Area.

During this inspection the following possible compliance issues were observed:

1. Location still shows signs of lack of stabilization from previous inspection on pad
2. No evidence of tracking control BMP's

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type Access		
comment:		
Corrective ActionL		Date:

Overall Good: ☐**Signs/Marker:**

Type CONTAINERS		
Comment:		
Corrective Action:		Date:
Type TANK LABELS/PLACARDS		
Comment:		
Corrective Action:		Date:
Type WELLHEAD		
Comment:		
Corrective Action:		Date:
Type BATTERY		
Comment: Signage is located at tank battery		
Corrective Action:		Date:

Emergency Contact Number:

Comment: 911	
Corrective Action:	Date: _____

Good Housekeeping:

Type DEBRIS		
Comment:		
Corrective Action:		Date:

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type IGNITOR/COMBUSTOR		
Comment:		
Corrective Action:		Date:
Type SEPARATOR		
Comment:		
Corrective Action:		Date:

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:	All meters have been calibrated on location within the past year.		
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Braden heads have a port for manual gauge monitoring Two (2) braden heads are tied into 100 bbl tank they are NOT open to tank at time of inspection		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	chemical tank at well heads		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	100 BBLs	STEEL AST		,	
Comment:	This tank is at well heads for braden heads					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Inspector Name: Ramsey, Scott

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	OTHER	HEATED STEEL AST		,	
Comment:	250 BBL tanks and one (1) is NOT heated					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	283775	Type:	WELL	API Number:	045-11993	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	283989	Type:	WELL	API Number:	045-12059	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	283990	Type:	WELL	API Number:	045-12064	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	283992	Type:	WELL	API Number:	045-12063	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	284741	Type:	WELL	API Number:	045-12259	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: tied into tank battery

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts				
		Ditches				
		Check Dams				

Comment:

This location is within a Density Habitat and Wildlife Management Area
 1. Location still shows signs of lack of stabilization from previous inspection on pad
 2. No evidence of tracking control BMP's

Corrective Action:

1. nstall or repair required BMPs in order to achieve stabilization on location
 2. Install, maintain or provide documentation of post construction management plan or BMP's

Date: 01/14/2021

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702294	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5351634