



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil at wellhead. See attached photo.		
Corrective Action:	Comply with Rule 608.e.		Date: 09/01/2020

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 243599 Type: WELL API Number: 123-11391 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<p><b>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679603398.</b>                      One out of two corrective actions were resolved. The remaining unresolved corrective action has been re-assigned to this location with its original corrective action date. COGCC's new rule reflects previous rule assigned in previous inspections in the narrative down below.</p> <p><b>COGCC Inspection Report Summary</b>                      **Weather Conditions: cloudy, dry ground                      On Thursday, February 4, 2021 at approximately 13:15, I, Inspector Brittani Santistevan, conducted an on-site inspection at STRONG 1-7 (KP Kauffman), at location #: 319516 in WELD COUNTY Colorado.                      While there, I observed a shut in wellhead.                      During this inspection the following possible compliance issues were observed:                      1. It appears stained soil has not been removed from underneath master valve. Per Rule 608.e. all production facilities, valves, pipes, fittings and vessels will be securely fastened or sealed, inspected at regular intervals and maintained in good mechanical condition. (Corrective Action Date: September 1, 2020) See attached photo #2.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	02/04/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402593728	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5346908">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5346908</a>
679603670	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5346900">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5346900</a>