

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/05/2021

Submitted Date:

02/05/2021

Document Number:

699802549

**FIELD INSPECTION FORM**

Loc ID 335029 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

25 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257807	WELL	PR	08/04/2000	GW	045-07597	SCARROW PA 34-36	PR
297889	WELL	PR	05/31/2009	GW	045-16991	DIAMOND ELK PA 343-36	PR
297890	WELL	PR	05/31/2009	GW	045-16992	DIAMOND ELK PA 333-36	PR
297891	WELL	PR	11/30/2009	GW	045-16993	DIAMOND ELK PA 443-36	PR
297892	WELL	PR	02/26/2009	GW	045-16994	DIAMOND ELK PA 543-36	PR
297893	WELL	PR	02/26/2009	GW	045-16995	DIAMOND ELK PA 44-36	PR
297894	WELL	PR	05/31/2009	GW	045-16996	DIAMOND ELK PA 433-36	PR
297895	WELL	PR	02/26/2009	GW	045-16997	DIAMOND ELK PA 434-36	PR
297896	WELL	PR	05/31/2009	GW	045-16998	DIAMOND ELK PA 534-36	PR
297897	WELL	PR	02/26/2009	GW	045-16999	DIAMOND ELK PA 444-36	PR
297898	WELL	PR	02/26/2009	GW	045-17000	DIAMOND ELK PA 544-36	PR
297899	WELL	PR	02/26/2009	GW	045-17001	DIAMOND ELK PA 344-36	PR
297900	WELL	PR	02/26/2009	GW	045-17002	DIAMOND ELK PA 334-36	PR

**General Comment:**

COGCC Inspection Report Summary

On Friday 2/5/21 at approximately 11:00 hours, I, Inspector Corey De Paolo, Conducted, an on-site inspection at TEP ROCKY MOUNTAIN LLC DIAMOND ELK-66S95W /36SWSE, Location #335029 in Garfield County Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Rutting present on location due to lack of stabilization. See photo #2821 and #2822. Stormwater is being obstructed and diverted due to sediment that has been pushed into ditch from a tire rut. See photo #2823, #2824 and #2825 with a corrective action date of 2/20/21.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign is weathered but still legible		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 13		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 13		
Comment:	All meter runs have been calibrated in the last year.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank by wellhead		
Corrective Action:		Date:	
Type: Plunger Lift	# 13		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 13		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
		Date:		

**Venting:**

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	257807	Type:	WELL	API Number:	045-07597	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	297889	Type:	WELL	API Number:	045-16991	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	297890	Type:	WELL	API Number:	045-16992	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	297891	Type:	WELL	API Number:	045-16993	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	297892	Type:	WELL	API Number:	045-16994	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	297893	Type:	WELL	API Number:	045-16995	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	297894	Type:	WELL	API Number:	045-16996	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	297895	Type:	WELL	API Number:	045-16997	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				

Facility ID:	297896	Type:	WELL	API Number:	045-16998	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	297897	Type:	WELL	API Number:	045-16999	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	297898	Type:	WELL	API Number:	045-17000	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	297899	Type:	WELL	API Number:	045-17001	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	297900	Type:	WELL	API Number:	045-17002	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
		Culverts				
		Ditches	Fail			Ditch has been diverted due to rutting
Gravel						
		Berms				
Berms						
		Sediment Traps				
Compaction	Fail					Rutting present on location
		Compaction				
Sediment Traps						
Ditches						

Comment: Rutting present on location due to lack of stabilization. See photo #2821 and #2822. Stormwater is being obstructed and diverted due to sediment that has been pushed into ditch from a tire rut. See photo #2823, #2824 and #2825.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 02/20/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402593730	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5346909">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5346909</a>
699802550	Photos for Insp. #699802549	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5346901">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5346901</a>