Inspector Name: Moran, Rick

FORM INSP

> Rev X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109





Inspection Date: 02/08/2021 Submitted Date: 02/16/2021

Document Number: 700405377

FIELD INSPECTION FORM

Loc ID	Loc ID Inspector Name:		On-Site	On-Site Inspection		<u>s</u>	Status Summary:				
315397 Moran, Rick			<u> </u>	2A Doc Num:			THIS IS A FOLLOW UP INSPECTION				
Operator I	nformation:					[FOLLOW UP INSPECT	ION REQU	JIRED		
OGCC Ope	erator Number:	51130				I	NO FOLLOW UP INSP	ECTION R	EQUIRED		
Name of O	perator: LOCIN OI	L CORPOR	 RATION			<u> </u>	Findings:				
Λ α Ι αΙ α α α α		2V FODEC	T DD #740				7 Number of Comme	nts			
Address: 2	2445 TECHNOLOG	of FORES	1 BD #/10				1 Number of Correcti	ve Actions			
City: TH	E WOODLANDS	State:	TX	Zip:							
							ANY CORRECTIVE AC PREVIOUS INSPECTION BEEN ADDRESSED A	ONS THÁT	HAVE NOT		
Contact In	formation:										
Contact Name Phone			ie	Email			Comment				
Thompson, Bud				BLThomps@BLM.gov							
Nicol, Michael 281-362 8600x11			mnicol@locinoil.com		l.com	All inspections					
Inspected	Facilities:										
Facility ID	Туре	Status	Status Date	e Well (Class	API Num	Facility Name		Insp Status		
000774	\A/E1.1	DD	04/04/0040	0)4/		402.00440	FORK UNIT FEDE	RAL 6-19	DD		

General Comment:

230771

follow up inspection of FIR documents:

1) 700404889 dated 1-7-2021.

WELL

2) 700405329 dated 2-4-2021.

The following compliance issues were resolved:

1) Gas leak.

The following compliance issues are uncompleted:

1) Bradenhead access not present. Photo 2. Complete by 2-8-2020.

PR

01/01/2019

OW

103-08440

-1-1W

This is a summary of inspection report 700405377.

PR

Inspector Name: Moran, Rick Location

			-	Location				
Overall Good: X								
Signs/Marker:								
Туре	WELLHEAD							
Comment:								
Corrective Action:		Date	:					
Туре	CONTAINERS							
Comment:								
Corrective Action:					Date	:		
Туре	TANK LABELS/PLACAI	RDS						
Comment:								
Corrective Action:					Date	:		
Туре	BATTERY							
Comment:								
Corrective Action:					Date	:		
Emergency Contact N	Number:							
Comment:								
Corrective Action:					Date:			
Overall Good: X								
Spills:								
Туре	Area	Volume						
In Containment: No								
Comment:								
Multilple Spills a	and Releases?							
Fencing/:								
Type	SEPARATOR							
Comment:								
Corrective Action:		Date:						
Type	TANK BATTERY							
Comment:								
Corrective Action:		Date:						
Туре	Type WELLHEAD							
Comment:								
Corrective Action:					Date:			
Equipment:						corrective date		
Type: Pump Jack # 1								
Comment:								
Corrective Action:					Date:			
Type: Vertical Heated	l Separator	# 1						

Inspector Name: Moran, Rick Comment: Corrective Action: Date: Type: Deadman # & Marked # 4 Comment: Corrective Action: Date: # 1 Type: Ancillary equipment Comment: Chemical container. Corrective Action: Date: # 1 Type: Bradenhead Comment: Bradenhead access is not present. Corrective Action: Provide bradenhead access with appropriate fittings to allow determination of pressure Date: 02/08/2021 and fluid flow. Type: Bird Protectors #2 Comment: Corrective Action: Date: Tanks and Berms: Contents Tank ID SE GPS Capacity Type PRODUCED WATER <50 BBLS Open Top Comment: Corrective Action: Date: **Paint** Condition Adequate Other (Content) Other (Capacity) 40 bbl Other (Type) Berms Permeability (Wall) Permeability (Base) Maintenance Type Capacity Earth Adequate Adequate Comment: Corrective Action: Date: Tank ID SE GPS Contents Capacity Type CRUDE OIL **300 BBLS** STEEL AST Comment: Corrective Action: Date: Paint Condition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

Inspector Name: Moran, Rick Туре Capacity Permeability (Wall) Permeability (Base) Maintenance Earth Adequate Adequate Comment: Corrective Action: Date: SE GPS Contents Capacity Tank ID Type CRUDE OIL 200 BBLS STEEL AST Comment: Corrective Action: Date: <u>Paint</u> Condition Adequate Other (Content) Other (Capacity) 210 bbl Other (Type) <u>Berms</u> Туре Capacity Permeability (Wall) Permeability (Base) Maintenance Earth Adequate Adequate Comment: Corrective Action: Date: Venting: Yes/No Comment: Corrective Action: Date: Flaring: Туре Comment: Corrective Action: Date:

Inspector Name: Moran, Rick

				<u>Inspecte</u>	d Facilities				
acility ID: _	230771	Type: _	WELL	API Number:	103-08440	Status: _	PR	Insp. Status:	PR
				Produc	ing Well			_	
	mment: PR								
Corrective	Action:							Date:	

Inspector Name: Moran, Rick

Reclamation - Storm Water - Pit								
Storm Water:								
BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment			
			Material Handling And Spill Prevention					
Comment: 4" of snow on plowed location.								
					Date:			
Pits: NO SURFACE INDICATION OF PIT								
	Maintenance 4" of snow on	BMP Lease Road Erosion BMPs 4" of snow on plowed location.	BMP Lease Road Erosion Maintenance BMP Maintenance 4" of snow on plowed location.	BMP Lease Road Erosion Maintenance BMPs Maintenance Material Handling And Spill Prevention 4" of snow on plowed location.	BMP Lease Road Erosion Maintenance BMPs Chemical BMPs Chemical BMP Maintenance Material Handling And Spill Prevention 4" of snow on plowed location.			

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
700405378	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5352625

Date Run: 2/16/2021 Doc [#700405377]