

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/08/2021

Submitted Date:

02/16/2021

Document Number:

700405397**FIELD INSPECTION FORM**
 Loc ID 315509 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10654Name of Operator: LASSO OIL & GAS LLCAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Boulger, Levin		lboulger@31operating.com	
Ikenouye, Teri		teri.ikenouye@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230956	WELL	SI	10/01/2019	GW	103-08625	C & K 2-24	SI

General Comment:

A follow up inspection of FIR documents
1) 700404758 dated 12-23-2020.

The following compliance issues were resolved:
1) Gas leak.

The following compliance issues are uncompleted:
1) Report past due monthly operations on Form 7. Complete by 1-11-2021.
2) Stormwater channel at lease road location entrance. Photos 5, 6. Complete by 2-1-2021.

Additional compliance issues:
1) Calibrate gas meter. Complete by 3-19-2021.

This is a summary of inspection report 700405397.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action: _____ Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Bradenhead access.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Last meter calibration June 2019.		
Corrective Action:	Meters need calibrated annually.	Date:	03/19/2021
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 230956 Type: WELL API Number: 103-08625 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last reported monthly operations were for May 2020. Report past due monthly operations. Last recorded production September 2019.

No audible gas flow at well or meter building.

Corrective Action: Submit required Form 7(s) to COGCC.

Date: 01/11/2021

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: Storm water channel going from lease road to location.Corrective Action: Install, maintain or provide documentation of post construction management plan or BMP's.Date: 02/01/2021**Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NO

Pit ID:

Lat:

Long:

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

Fencing:Fencing Type: WildlifeFencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700405398	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5352637