

Inspection Photos

API: 071-08925

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08925 | Date: 2/12/2021

Inspection Photos



Photo 1. Facing west along the access road. Outlet protection was installed at the culvert. Rock rip/rap is installed where gully erosion was identified.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08925 | Date: 2/12/2021

Inspection Photos



Photo 2. Facing west along the access road. Outlet protection was installed at the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08925 | Date: 2/12/2021

Inspection Photos



Photo 3. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08925 | Date: 2/12/2021