

Inspection Photos
Operator: Simcoe
API: 067-09354
Date: 2/11/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the northern fill slope from the northeastern corner facing westward. Revegetation appears to be progressing with crested wheatgrass observable.



Photos 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4 View of musk thistles within the interim reclamation area. Approximately 1000 individuals observed.



Photo 5. View of the reference area comprised of pinyon/juniper woodland with understory of sagebrush, antelope bitterbrush, gambel oak, and blue grama.